

CCWD Water Manager Report September - October 2021

Sep. 14

Had an unusual drop in the round tank water level.

I went searching for a leak and found one at the end of the line going to the property across from the community center.

That line has its own shut-off valve, so I was able to isolate the leak without effecting any other properties.

I dug it up and found the leak was from a

cracked tee fitting for the blowoff

the fitting had concrete poured around it

and when the pipe expanded

it cracked the fitting.

Switched to block tank.

Sep. 16

I repaired the leak so it would no longer put pressure on the fitting. I left the hole open for a week to monitor the repair for leaks.

Sep. 17

Switched to the round tank.

Sep. 23

Filled in the hole from the leak repair.

Oct. 8

Switched to block tank.

Oct. 11

Switched to round tank.

Oct. 19

Mooney Well didn't run.

Oct. 20

Mooney Well gave an error code for
an open lead (loose wire)

I checked for loose or corroded wires

I found none.

Oct. 29

Replaced a corroded fitting next to the meter
on the Mooney Well.

Oct. 30

Ran Peterson well to maintain water level in the round tank.

Oct. 31

While reading water meters I noticed a couple of compression fittings were slipping out. Notified everyone the water would be off for about 1hr. I shut off the water loosened the fittings straightened the pipe and tightened the fittings. Then finished reading the meters.

Nov. 6

Ran Peterson well to maintain water level in the round tank.

Nov. 8

Robert Saxton from Saxton pump came out to check Mooney Well.

Nov. 12

Robert Saxton came back to pull the pump from the well. Ran Peterson well to bring the water level in the round tank up before switching to the block tank.