last longer, we have enclosed these simple instructions.

Important

For best performance... Always do the following:

1. The Jet Swet™ must be inserted as far as possible through the valve or fitting into the pipe to place the gasket as far from the head as possible. Where this is not possible, place a wet rag etc. or grease with