

Water Manager Report Sept 2023

June 22

Turned off Mooney well to save electricity.

June 25

Aaron Ross replaced the control box on the solar system at Mooney Well.

June 30

Read meters

July 1

I found a leak on Carl McKenney's service line between his meter and house.

With the help of Jerry Bucheit
We repaired the leak.

July 7

Water sample taken from
455 Canebrake Rd. came back
positive for coliform.

July 10

G. Ramstrum and Dean Kuns
Took water samples from
425 Canebrake and 185 Canyon
Both came back positive for coliform.

July 13

Dean Kuns
Took water samples from
Peterson and Mooney wells.
G. Ramstrum
Delivered them to the Lab.
Both wells tested absent for coliform.

July 15

G. Ramstrum and Dean Kuns
Went to El Centro to pick up chlorine
to disinfect the system.

July 17

G. Ramstrum , Chris Macdonald
Jerry Bucheit and Dean Kuns
Poured chlorine into the round tank
to start the treatment of the system.

July 18

G. Ramstrum , Chris Macdonald
Jerry Bucheit and Dean Kuns
Opened blow offs to pull the chlorine
through the whole system.

July 19

G. Ramstrum , Chris Macdonald
Jerry Bucheit , Daryl Holmes Jr. and
Dean Kuns
Began flushing the chlorine from the lines with fresh water.
Ran Peterson well.

July 20

G. Ramstrum , Chris Macdonald
Jerry Bucheit , Daryl Holmes Jr. and
Dean Kuns
Finished flushing chlorine from the lines.
Ran Peterson Well
Jerry Bucheit and Dean Kuns
Took water samples and
G. Ramstrum delivered to the lab.
Results came back absent for coliform.

July 27

A swarm of bees showed me a small
leak on the Price line behind
Carl McKenney's house.
I went back at sundown and with the
help of Chris Macdonald we fixed
the leak.

Aug. 4

Peterson Well didn't run and I couldn't
get it to run on manual.

Aug. 5

Robert Sexton came to check it out and
found the problem was the control box.

Aug. 6

Robert Sexton replaced the control box.
Ran Mooney Well.

Aug. 7

G. Ramstrum informed me of a wet spot by a blow off on Upward Trail. We dug it up and found a leak on the main line 3' deep. We were unable to fix it at that time due to heat and bees. We came back when the bees left and it cooled off. With additional help from Chris Macdonald and Bob Mooney We completed the repair.

Aug. 9

We turned the water on and had a failure at the compression coupling.

Aug. 10

We cleaned out the hole and removed the pipe plugged the open ends of the pipe. Returned after sundown and did the repair minus the compression coupling and blow off the riser.

Aug. 11

Checked the repair turned the water on and blew the air out of the line

Aug. 19

Shut off the round tank for the storm.

Aug. 21

Inspected the Price line turned the round tank back on and blew the air out of the line.

Aug. 31

Read meters