

EQUIPMENT REPORT September 10 2022

Equipment usage since last report, June 11 2022

WATER DISTRICT

Backhoe 0 hr.

Dump truck 0 hr

PRIVATE PROPERTY

Backhoe 0 hr

DUMP truck 0 hr

EQUIPMENT MAINTENANCE

Backhoe

Dump truck New carburetor installed

Ford Ranger Front suspension needs ball joint bushings

Generator Has been started and run

Backhoe Has been started and run.

EZ GO Workhorse needs starter / alternator

Submitted by equipment operator

Ron Akey