

Water Manager Report
Canebrake County Water District
September 12, 2020

June 24

Dean Kuns installed a screen over the overflow pipe for the round tank.

July 1

Ellyn Hae, John Berthe, Frank Colver & Dean Kuns covered the new pipeline. Natalie Spandau took pictures.

July 21

Dean Kuns fixed a slight leak on the blowoff valve at Canebrake & staghorn. Tightened the packing nut. The repair was easy after I removed the swarm of BEES! They like that water in the summertime. Thank You Karyn Sauber for finding the leak.

July 26

Dean Kuns replaced the meter on Mooney well. Found a lot of corrosion on the intake of the old meter.

July 27

Dean Kuns repaired a leak near Daryl Holmes Jr.'s water meter. The pipe had a large rock on it. Thanks Daryl Holmes Jr for pointing out the damp spot.

Aug. 15

Frank Colver, Bob Mooney & Dean Kuns repaired a compression coupling that was slipping out but not yet leaking. We had some issues with the new shutoff valve. It was very tight and hard to turn. This will be fixed before covering the valve.

Thanks to Keith Foulds for the cases of water.

Water Manager
Dean Kuns